

EDD Warning Log

Lab Reporting Batch ID: 006555

eQAPP: GSIPacific_MakuaMilitaryRes_031814

Laboratory: ARDL

Table	Line #	Column	Value	Warning Description
Sample Methods	9			A 'Method_Blank' is not reported for PreparationBatch '1203JFSZ' for Method '8260C' and Matrix 'Tissue'. The project eQapp requires a 'Method_Blank' sample for this method and matrix.
Sample Methods	9			A 'Laboratory_Control_Sample' is not reported for PreparationBatch '1203JFSZ' for Method '8260C' and Matrix 'Tissue'. The project eQapp requires a 'Laboratory_Control_Sample' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike' is not reported for MethodBatch '1203JFSZ' for Method '8260C' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike_Duplicate' is not reported for MethodBatch '1203JFSZ' for Method '8260C' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike_Duplicate' sample for this method and matrix.
Sample Methods	9			A 'Method_Blank' is not reported for PreparationBatch 'B10114' for Method '8081B' and Matrix 'Tissue'. The project eQapp requires a 'Method_Blank' sample for this method and matrix.
Sample Methods	9			A 'Laboratory_Control_Sample' is not reported for PreparationBatch 'B10114' for Method '8081B' and Matrix 'Tissue'. The project eQapp requires a 'Laboratory_Control_Sample' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike' is not reported for MethodBatch 'B10114' for Method '8081B' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike_Duplicate' is not reported for MethodBatch 'B10114' for Method '8081B' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike_Duplicate' sample for this method and matrix.
Sample Methods	9			A 'Method_Blank' is not reported for PreparationBatch 'B6637' for Method '8330A' and Matrix 'Tissue'. The project eQapp requires a 'Method_Blank' sample for this method and matrix.
Sample Methods	9			A 'Laboratory_Control_Sample' is not reported for PreparationBatch 'B6637' for Method '8330A' and Matrix 'Tissue'. The project eQapp requires a 'Laboratory_Control_Sample' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike' is not reported for MethodBatch 'B6637' for Method '8330A' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike_Duplicate' is not reported for MethodBatch 'B6637' for Method '8330A' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike_Duplicate' sample for this method and matrix.
Sample Methods	9			A 'Method_Blank' is not reported for PreparationBatch 'B6640' for Method '8270C' and Matrix 'Tissue'. The project eQapp requires a 'Method_Blank' sample for this method and matrix.
Sample Methods	9			A 'Laboratory_Control_Sample' is not reported for PreparationBatch 'B6640' for Method '8270C' and Matrix 'Tissue'. The project eQapp requires a 'Laboratory_Control_Sample' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike' is not reported for MethodBatch 'B6640' for Method '8270C' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike' sample for this method and matrix.
Sample Methods	9			A 'Matrix_Spike_Duplicate' is not reported for MethodBatch 'B6640' for Method '8270C' and Matrix 'Tissue'. The project eQapp requires a 'Matrix_Spike_Duplicate' sample for this method and matrix.