


R:\new\j397\FigureK-4.cdr - 03/13/03 - CT




Source: Uribe and Associates 1996

Schofield Barracks Main Post and Schofield Barracks East Range Installation Restoration Program Investigation Sites

Legend

-  Building
-  Fence
-  Surface Water



Site Included in OU 3 Remedial Investigation

### Site Locations - Operable Unit 3 Schofield Barracks East Range

O'ahu, Hawai'i  
**Figure K-4**