

Source: Uribe and Associates 1996

R:\new\J397\FigureK-4.cdr - 03/13/03 - CT

Schofield Barracks Main Post and
Schofield Barracks East Range
Installation Restoration Program
Investigation Sites

Legend

Building

Fence

Surface Water

61 Site Included in OU 3
Remedial Investigation

Site Locations - Operable Unit 3
Schofield Barracks East Range

O‘ahu, Hawai‘i

Figure K-4